

D.L. Ricci Corp. Case Study #314



"Big BU to the Rescue"

Set-Up:

- We prepared by having our product and people ready at a moments notice
- An upper Midwest refinery was undergoing some outage maintenance work disassembling a flange when their contactor went into the gasket surface
- They needed the surface refinished and they needed it done now

Plan:

- The emergency call went out to D.L. Ricci Corp.
- The volume of this gasket made the BU 110 the obvious choice and we had one ready to go
- This call coming in the middle of our busy season meant a crew of this size was not going to be easy but 10 were picked
- This would have to be a 24/7 field job

Operation:

- Within an hour of receiving the call we had our BU110 onsite and 4 men for 5 shifts of flanging
- With an outdoor site, the crew had to put up with plenty of rain and cold
- The BU110 performed as promised and flanging was done efficiently

Results:

- The flange was resurfaced and the refinery was back on schedule
- The BU110 proved its durability & portability in these harsh conditions
- The client was ecstatic, "D.L. Ricci Corp. came through"



Before



After

